

HB-30[®] one shot

Ice machine cleaner and disinfectant

Unavoidable by their nature, Limescale and slime are two of the most common problems with ice machines. HB-30 one shot is a high strength descaler and disinfectant that will easily tackle these issues. Just one bottle will quickly go to work on virtually all types of ice machines - it's sophisticated formulation is not only highly concentrated but is inhibited too. A small footprint means the bottle will take up no room at all in the back of the van, yet just one bottle will virtually always provide enough product to do the job.

Specification

| | |
|-----------------------------|---|
| Name | HB-30 one shot |
| Product Code | 010148 |
| Packing Quantity | 12 x 250ml |
| Packing Size (L x H x D) cm | 23 x 20 x 18 |
| Shipping Weight (Kg) | 4.74 |
| Shipping Volume (m3) | 0.0324 |
| Application | Ice Machine Cleaner |
| Soils | Scale, Bacteria, Mould, Fungus |
| Dilution (water:product) | 40:1 |
| Contact Period | 30 Minutes |
| Rinse/Flush Required | YES |
| Special Features | Disinfectant, Metal Safe Odourless, Non Fuming |



Directions for use

Turn off the refrigeration on the ice machine, leaving the pump in operation if possible. Drain the machine and refill with 10 litres of fresh water. Add one bottle of HB-30 one shot to the 10 litres of water and allow the solution to circulate for about 30 minutes. Brush the cleaning solution onto any scaled surfaces which have not come into contact with the circulating HB-30 one shot. Ice machines which are very heavily scaled may require the cleaning process to be repeated with another bottle of HB-30 one shot. After completing the cleaning process, drain the HB-30 one shot solution and then flush thoroughly with fresh water.



HB-30[®] one shot
Corrosive
UN1903

Contains Phosphoric Acid

R34: Causes burns. S36/37/39: Wear suitable protective clothing, gloves and eye / face protection. S1/2: Keep locked up and out of the reach of children. S26: In case of contact with eyes, rinse immediately with plenty of water and seek medical advice. S45: In case of accident or if you feel unwell, seek medical advice immediately (show the label where possible). S24/S25: Avoid contact with skin & eyes. S23: Do not breathe vapour.

Consult Safety Data Sheet for full safety information. Always wear suitable PPE.



Advanced Engineering Ltd
Guardian House, Stroudley Road
Basingstoke, Hants, RG24 8NL. UK
Tel: +44(0)1256 460300
sales@advancedengineering.co.uk
www.advancedengineering.co.uk